

No: 000317

CHRISTEN INDUSTRIES, INC.  
1048 SANTA ANA VALLEY ROAD  
HOLLISTER, CALIFORNIA 95023  
TELEPHONE: (408) 637-7405

By: FLC

Date: 06-03-83

Page: 1 of 1

Send To: 904 FUSELAGE KIT

000317 904 0000  
C CHRISTEN INDUSTRIES INC.  
U 1048 SANTA ANA VALLEY RD.  
S HOLLISTER, CA 95023  
T

Subject: INSPECTION OF LANDING  
GEAR SUPPORT STRUCTURE  
ON FUSELAGE OF EAGLE II  
AIRCRAFT

\*\*\* IMPORTANT! RESPONSE TO THIS LETTER MAY BE CRITICAL FOR FLIGHT SAFETY. \*\*\*


The landing gear strut on the Eagle II aircraft is a single piece of AA 2024 aluminum heat treated to T6 condition. It is attached to the tubular fuselage structure on both sides with bolts and clamping plates. The clamping area of the fuselage structure is heavily reinforced with tubular elements which transfer bending and torsional loads to other areas of the structure. As a part of the landing gear design the fuselage structure was statically tested and found to exceed by more than 200% the requirements of FAR Part 23.

The landing gear system has been tested for more than four years on the Eagles Team and factory demonstrator aircraft, all of which have more than 1000 hours of flight time and hundreds of landings under a great variety of conditions. Regular inspections of these aircraft indicate that the landing gear strut and the associated fuselage structure are performing well and as expected with no evidence of corrosion, wear, or structural problems.


An Eagle builder recently reported discovering cracks in the lower longerons of his fuselage structure immediately adjacent to the landing gear clamping area. His aircraft has less than 200 flight hours and he does not recall any unusual usage or landing situations which could have overstressed the landing gear system. We cannot account for this apparent structural failure, and it conflicts with inspection reports provided by other Eagle aircraft operators and with factory testing and inspection experience. The aircraft will be repaired at the factory under warranty, and information from field inspections of other Eagle II aircraft will be reviewed carefully by factory personnel to verify that this is the only incident of its kind.

ALTHOUGH WE THINK IT IS UNLIKELY THAT CRACKS WILL BE FOUND IN OTHER EAGLE II AIRCRAFT, ALL AIRCRAFT which are finished and flying SHOULD BE INSPECTED for cracks in the tubular elements of the fuselage structure adjacent to the landing gear attachment PRIOR TO THE NEXT FLIGHT. Please refer to the area identified on the enclosed Engineering Sketch X-90165. This inspection should also be performed at the regular intervals specified in Section 8 (Maintenance) of the 924 Flight Kit product manual. Any evidence of wear, cracking, or other irregularities should be reported immediately to Frank Christensen, Ivan Clede, or Dan Beck at the Christen factory.

ENCLOSURES: ENGINEERING SKETCH X-90165






TUBULAR ELEMENTS WHICH SUPPORT LANDING GEAR STRUT AND WHICH TRANSFER TORSIONAL AND BENDING LOADS TO OTHER AREAS OF FUSELAGE STRUCTURE.



INSPECT FOR CRACKS ON ALL SURFACES OF ALL TUBULAR ELEMENTS IN THIS AREA ON BOTH SIDES OF FUSELAGE AS A PART OF REGULAR INSPECTIONS.


LANDING GEAR STRUT

<b>UNLESS OTHERWISE SPECIFIED:</b>  TOLERANCES: FRAC. $\pm$ 1/64 DEC. XXX $\pm$ .005 ANGLES $\pm$ 0° 30'  DIMENSIONS IN INCHES DO NOT SCALE DRAWING	MATERIAL AND CONDITION NOTED		 CHRISTEN INDUSTRIES HOLLISTER, CALIFORNIA	
	FINISH NONE			
DRAWN BY I. CLEDE	DATE 5-31-83	PROJECT EAGLE II AIRCRAFT		TITLE GEAR SUPPORT INSPECTION
APPROVED BY 	DATE 5-31-83	CODE NO. PA X- 90165		ISSUE



OXY-ACETYLENE TORCH WITH  
LARGE MULTI-NOZZLE TIP  
SET TO LARGE FLAME.

1st STEP: HEAT LOWER LONGERON AND ASSOCIATED TUBING CLUSTERS AND CLAMP PLATES TO CHERRY RED COLOR AND ALLOW TO SLOWLY AIR COOL TO ANNEAL. PAINT WILL OXIDIZE AWAY, LEAVING A LIGHT GRAY COLOR.




REMOVE 3/8" TUBES


↑ OPEN TO FULL I.D. OF LONGERON

2nd STEP: CUT AND GRIND FORWARD END OF LOWER LONGERON TUBING CLUSTER AND ENGINE MOUNT WASHER FROM CENTERLINE OF LOWER LONGERON TO FULL INSIDE DIAMETER OF LOWER LONGERON.


CUT OUT VERTICAL 3/8 IN. DIA TUBING MEMBERS (DASHED OUTLINE) AND GRIND AWAY REMAINING TUBING STUBS AND WELD AREAS AT BOTH ENDS TO PRODUCE SMOOTH TUBING SURFACES.

NOTE: ALL STEPS SHOULD BE PERFORMED ON BOTH SIDES OF THE FUSELAGE STRUCTURE.

UNLESS OTHERWISE SPECIFIED:	MATERIAL AND CONDITION			 CHRISTEN INDUSTRIES HOLLISTER, CALIFORNIA <b>ENGINEERING SKETCH</b>		
	NOTED					
TOLERANCES: FRAC. ± 1/64 DEC. XXX ± .005 ANGLES ± 0° 30'	FINISH			TITLE		
	NONE					
DIMENSIONS IN INCHES DO NOT SCALE DRAWING	DRAWN BY	DATE	PROJECT	FUSELAGE LONGERON REPAIR		
	I. CLEDE	6-8-83	EAGLE II AIRCRAFT			
	APPROVED BY	DATE		CODE	NO.	ISSUE
	<i>[Signature]</i>	6-8-83		PA	X- 90169 1 of 3	B




3rd STEP: DRILL FIVE 1/4 IN. DIA HOLES IN LOWER LONGERON FOR ROSETTE WELDS.



4th STEP: APPLY CUTTING OIL LIBERALLY TO INSIDE OF LONGERON THRU HOLES DRILLED FOR ROSETTE WELDS AND REAM LOWER LONGERON TO CLEAR INTERNAL WELDS AND DISTORTED AREAS TO A DEPTH ABOUT 1/4 IN. LONGER THAN THE LENGTH OF THE INTERNAL SUPPORT TUBE SUPPLIED IN REPAIR KIT.


UNLESS OTHERWISE SPECIFIED:  TOLERANCES: FRAC. ± 1/64 DEC. XXX ± .005 ANGLES ± 0° 30'  DIMENSIONS IN INCHES DO NOT SCALE DRAWING	MATERIAL AND CONDITION			<b>CHRISTEN</b> <small>CHRISTEN INDUSTRIES HOLLISTER, CALIFORNIA</small>	
	NOTED				<b>ENGINEERING SKETCH</b>
	FINISH			TITLE	
	NONE			FUSELAGE LONGERON REPAIR	
DRAWN BY	DATE	PROJECT	CODE	NO.	ISSUE
L. CLEDE	6-8-83	EAGLE II AIRCRAFT	PA	X- 90169	2 of 3
APPROVED BY	DATE				
<i>[Signature]</i>	6-8-83				C




5th STEP: DRIVE INTERNAL SUPPORT TUBE INTO LONGERON JUST FAR ENOUGH SO THAT PLUG WHICH FITS ON FORWARD END OF SUPPORT TUBE IS FLUSH WITH FRONT SURFACE OF ENGINE MOUNT WASHER.

TACK-WELD AT EACH HOLE IN LOWER LONGERON AND AROUND PLUG AND FORWARD END OF SUPPORT TUBE. ROSETTE WELD EACH HOLE IN LONGERON, WELD COMPLETELY AROUND CRACK IN LONGERON, AND WELD COMPLETELY AROUND PLUG IN FORWARD END OF SUPPORT TUBE.

TACK-WELD AND THEN WELD NEW 1/2 IN. DIA VERTICAL TUBES SUPPLIED IN REPAIR KIT



6th STEP: TACK-WELD PATCH. HEAT AND FORM PATCH AS NECESSARY TO MAINTAIN CLOSE CONTACT WITH LONGERON. WELD COMPLETELY AROUND OUTER EDGE. GRIND OR FILE WASHER AREA SMOOTH AND FORWARD OUTER SURFACE OF PATCH TO CLEAR FIREWALL MOUNTED FUSELAGE SIDE PANELS. RE-HEAT ALL PARTS TO CHERRY RED COLOR TO ANNEAL AND RELIEVE STRESSES. REPAINT OXIDIZED AREAS TO PREVENT CORROSION.

UNLESS OTHERWISE SPECIFIED:	MATERIAL AND CONDITION			 CHRISTEN INDUSTRIES HOLLISTER, CALIFORNIA	
	NOTED				ENGINEERING SKETCH
	FINISH				
TOLERANCES; FRAC. ± 1/64 DEC. XXX ± .005 ANGLES ± 0° 30'	NONE			TITLE FUSELAGE LONGERON REPAIR	
	DRAWN BY	DATE	PROJECT		
DIMENSIONS IN INCHES	I. CLEDE	6-8-83	EAGLE II AIRCRAFT	CODE NO.	
DO NOT SCALE DRAWING	APPROVED BY	DATE		ISSUE	
	<i>[Signature]</i>	6-8-83		PA X- 90169 3 of 3 D	