

AVIAT AIRCRAFT INC.

672 South Washington
P.O. Box 1240
Afton, WY 83110
307-885-3151
facsimile: 307-885-9674
e-mail: aviat@aviataircraft.com


Service Letter #2

Date: September 24, 2003
Subject: Husky Horizontal Stabilizer Threaded Terminal Replacement
Models Affected: Aviat Husky A-1A S/N 1396 and up and A-1B 2001-2247
To: The owners or operators of the Huskies specified above

Several incidents in the field have indicated that the threaded terminal, installed on the Aviat Husky A-1A and A-1B horizontal stabilizer strut, has a service life that may be limited to between two and five hundred hours. Aviat's engineering department has voluntarily researched the cause of this life-limit and developed a new terminal with a greatly increased service life as a solution.

Aviat highly recommends that the owners or operators of the airplanes mentioned above to replace the horizontal stabilizer strut threaded terminal, Aviat P/N 35648-001 with the redesigned part 35648-002, as soon as conveniently possible in order to eliminate any possibility of in-flight failure. Please contact our parts department to purchase the parts, and reply with the attached letter stating compliance with Engineering's recommendations.

Cordially,



Daniel J. Ruhl
Mechanical Design Engineer
Aviat Aircraft Inc.