

# SERVICE BULLETIN

DATE: 05-28-99

**SERVICE BULLETIN No. 17**  
ENGINEERING ASPECT ARE FAA APPROVED  
Engineering Order: 2732 (3/28/96)

REVISION: n/c

SUBJECT: Trim Control System Adjustment

MODELS AFFECTED: Husky A-1 (Ser.No.Eff: 1001-1329)

TIME OF COMPLIANCE: At Owners Discretion

After continuous usage, we have found that the Elevator Trim Control Cables used on early model A-1 Husky, we found that the original cable assemblies may not have the proper length for adequate travel limits.

We have subsequently redesigned 35284-501 (lengthened) and 35284-504 (shortened) cable assemblies for use on all production aircraft, and suggest that if travel limits are not adequate on aircraft in the field, that they be replaced with the new length cable assemblies.

We feel that not all assemblies in the field will require this change, however we have available a kit for replacement of the affected aircraft and may be obtained by contacting Aviat Aircraft Inc. at Afton, Wyoming.

Kit Contents: 1 each P/N: 35284-501 Cable Assembly  
1 each P/N: 35284-504 Cable Assembly

---

Aviat Aircraft Inc. Representative