

No: 000179

CHRISTEN INDUSTRIES, INC.
1048 SANTA ANA VALLEY ROAD
HOLLISTER, CALIFORNIA 95023
TELEPHONE: (408) 637-7405

By: IC Date: 10-16-80 Page: 1 of 1

Send To: 902 LOWER WING KIT
902-S 902-S

C-0002
C CHRISTEN INDUSTRIES INC.
U 1048 SANTA ANA VALLEY RD.
S HOLLISTER, CA 95023
T

Subject: POSSIBILITY OF DEFECTIVE
THREADS IN 50130-009 AND
50130-010 TIE ROD
TERMINALS.

An Eagle builder reports that one of the tie rod terminals used to attach the flying wires to the aircraft structure *and a right hand* [REDACTED] pattern. This defect results from a vendor manufacturing error and it results in a weak part.

Please inspect all the tie rod terminals provided in your kits to verify that only one thread pattern is present. The 50130-009 tie rod terminal has a left hand thread pattern. The 50130-010 tie rod terminal has a right hand thread pattern.

If you have a tie rod terminal with two thread patterns, please mail the part directly to the Christen factory and telephone the factory collect to request a replacement part under warranty.

Enclosures:

None