

# AVIAT AIRCRAFT INC.

---

672 South Washington  
P.O. Box 1240  
Afton, WY 83110  
307-885-3151  
facsimile: 307-885-9674  
e-mail: [aviat@aviataircraft.com](mailto:aviat@aviataircraft.com)

## ***Service Letter #1***

Date: 3-21-2002  
Subject: Husky Flap Hardware Inspection  
Models Affected: All Christen and Aviat Huskys

---

To those Husky owners specified above,

This service letter has been posted to remind the owners of all Husky A-1, A-1A, and A-1B aircraft of the importance of thoroughly inspecting all control systems, including the cable attachment hardware, cables, and pulleys at every 100-hr and annual inspection.

Cordially,



Daniel J. Ruhl  
Mechanical Design Engineer  
Aviat Aircraft Inc.