

CHRISTEN \*

PRODUCT LETTER

No: 000108

CHRISTEN INDUSTRIES, INC.  
1048 SANTA ANA VALLEY ROAD  
HOLLISTER, CALIFORNIA 95023  
TELEPHONE: (408) 637-7405

By: IC            Date: 11-26-79            Page: 1 of 1

Applies: 918 ENGINE EQUIPMENT KIT

C-0002  
C CHRISTEN INDUSTRIES INC.  
U 1048 SANTA ANA VALLEY RD.  
S HOLLISTER, CA 95023  
T

Subject: VENDOR-SUPPLIED 50188-001  
ADAPTER IMPROPERLY  
MACHINED

THE VENDOR SUPPLIED 50188-001 ADAPTER PROVIDED IN YOUR 918 KIT HAS IMPROPERLY MACHINED THREADS AND SHOULD NOT BE INSTALLED IN THE OIL TEMPERATURE SENSOR PORT OF YOUR LYCOMING AIRCRAFT ENGINE.

OPERATION OF YOUR AIRCRAFT ENGINE WITH THE ORIGINALLY SUPPLIED 50188-001 ADAPTER IS NOT RECOMMENDED BECAUSE LUBRICATING OIL UNDER PRESSURE WILL LEAK FROM THE OIL TEMPERATURE SENSOR PORT.

REPLACEMENT 50188-001 ADAPTERS ARE NOW BEING MANUFACTURED AND WILL BE SENT TO YOU VIA MAIL WHEN THEY ARE AVAILABLE.

DISCARD THE ORIGINAL 50188-001 ADAPTER.

ENCLOSURES:

NONE