

CHRISTEN *

PRODUCT LETTER

No: 000149

CHRISTEN INDUSTRIES, INC.
1048 SANTA ANA VALLEY ROAD
HOLLISTER, CALIFORNIA 95023
TELEPHONE: (408) 637-7405

By: IC Date: 03-13-80 Page: 1 of 1

Send To: 907 FUSELAGE EQUIPMENT KIT

C-0002

C CHRISTEN INDUSTRIES INC.
U 1048 SANTA ANA VALLEY RD.
S HOLLISTER, CA 95023
T

Subject: CORRECTION OF STABILIZER
INCIDENCE ANGLE IN MANUAL

Due to an error in manual step B-25 the stabilizer incidence is incorrectly listed as two degrees positive. The actual stabilizer incidence measured from the upper longerons in the cockpit area is one degree.

The correct elevator travel relative to the horizontal stabilizer is 26 degrees up travel and 28 degrees down travel.

Manual step B-23 should call for a 39 degree down angle relative to level. The 40 degree angle shown is incorrect.

Manual step B-24 should call for a 15 degree up angle relative to level. The 14 degree angle shown is incorrect.

These changes will be included in the next manual revision.

Enclosures:

None