

CHRISTEN *

PRODUCT LETTER

CHRISTEN INDUSTRIES, INC.
1048 SANTA ANA VALLEY ROAD
HOLLISTER, CALIFORNIA 95023
TELEPHONE: (408) 637-7405

By: FLC

Date: 04-27-80

No: 000158

Page: 1 of 1

Send To: 923 COVERING & PREFINISH KIT

C-0002

C CHRISTEN INDUSTRIES INC.
U 1048 SANTA ANA VALLEY RD.
S HOLLISTER, CA 95023
T

Subject: REPLACEMENT OF FILAMENT
TAPE IN EAGLE II AIRCRAFT
923 COVERING AND PRE-
FINISH KITS

Due to a part identification error, the 50256-001, 50256-003, and 50256-004 filament tape supplied in your 923 Series Covering and Prefinish Kit is not the correct material. The tape supplied is similar in appearance to the correct tape, but it has lower filament density and will not be as durable over long periods of time.

The tape is applied over fabric at the locations of rib stitching in the covering process. It functions as a reinforcement of the fabric to prevent the lacing cord from pulling through the fabric under high air loads.

A supply of the correct tape is being sent to you via UPS prepaid. We recommend that you discard the previously supplied tape to prevent it from being used accidentally in place of the correct tape.

ENCLOSURES:

In separate package:

1 r1 50660-001 Tape
1 r1 50660-003 Tape
1 r1 50660-004 Tape