

CHRISTEN *

PRODUCT LETTER

No: 000198

CHRISTEN INDUSTRIES, INC.
1048 SANTA ANA VALLEY ROAD
HOLLISTER, CALIFORNIA 95023
TELEPHONE: (408) 637-7405

By: IC Date: 01-27-81 Page: 1 of 1

Send To: 923 COVERING & PREFINISH KIT

C-0002

C CHRISTEN INDUSTRIES INC.
U 1048 SANTA ANA VALLEY RD.
S HOLLISTER, CA 95023
T

Subject: INSPECTION PLATES
 SUPPLIED IN 923 KIT

There is a possibility that inspection plates of an incorrect type may have been packaged in your 923 Covering and Prefinish Kit. The incorrect inspection plates can be identified easily by the shape of the retaining spring which is approximately 1/4 inch shorter in length than the outside diameter of the inspection plate and which is bent up 90 degrees at each tip. The correct inspection plate has a retaining spring which is not bent up and which extends 3/16" beyond the outside diameter of the plate on each side.

Please examine the inspection plates supplied in your kit and telephone the Christen factory collect if replacement 50262-001 inspection plates are required.

Enclosures:

None