

No: 000228

CHRISTEN INDUSTRIES, INC.
1048 SANTA ANA VALLEY ROAD
HOLLISTER, CALIFORNIA 95023
TELEPHONE: (408) 637-7405

By: FLC Date: 05-27-81 Page: 1 of 1

Send To: 908 COCKPIT EQUIPMENT KIT

C DRAFT COPY
U
S
T

Subject: RUDDER CABLES OMITTED
FROM 908 COCKPIT EQUIP-
MENT KIT

Due to a packaging error, there is a possibility that your 908 Kit may have been shipped with 1 ea 31085-501 and 1 ea 31085-502 Rudder Cable Assemblies rather than 2 ea of these parts which are required.

Please check the contents of your 908 Kit, and if any of the rudder cables were omitted, telephone the Christen factory collect to request that a replacement be sent to you via air mail immediately.

We apologize for this possible error in the assembly of your 908 Kit, and we hope that it will not cause you inconvenience.

Enclosures:

None