

No: 000256

CHRISTEN INDUSTRIES, INC.  
1048 SANTA ANA VALLEY ROAD  
HOLLISTER, CALIFORNIA 95023  
TELEPHONE: (408) 637-7405

By: FLC      Date: 03-02-82      Page: 1 of 1

Send To: 908 COCKPIT EQUIPMENT KIT

C \*\* AFFIX LABEL HERE \*\*  
U  
S  
T

Subject: INCORRECT CLEVIS BOLTS  
SUPPLIED WITH PREVIOUS  
PRODUCT LETTER 000251

Due to an administrative error the clevis bolts supplied with the subject product letter were an incorrect size. The bolts supplied were Christen Part 50825-011 (AN21-11, 6-40UNF X 23/32 long). The correct bolt is Christen Part 50825-081 (AN23-11, 10-32UNF X 23/32 long). The castle shear nuts and washers supplied were the correct size.

The correct clevis bolts are being sent as replacements to all Christen customers to whom the 908 Cockpit Equipment Kit has been supplied. Installation of the replacement bolts should be performed in accordance with the original Product Letter 000251.

ENCLOSURES: 2 EA 50825-081 CLEVIS BOLTS