

No: 000291

CHRISTEN INDUSTRIES, INC.
 1048 SANTA ANA VALLEY ROAD
 HOLLISTER, CALIFORNIA 95023
 TELEPHONE: (408) 637-7405

By: FLC Date: 02-21-83 Page: 1 of 1

Send To: 915 CANOPY KIT

C-0002

C CHRISTEN INDUSTRIES INC.
 U 1048 SANTA ANA VALLEY RD.
 S HOLLISTER, CA 95023
 T

Subject: ADDITION OF CANOPY ROLLER
 ASSEMBLY TO EAGLE II
 AIRCRAFT 915 CANOPY KIT

A guide roller assembly has been added to the left rear canopy retaining pin support arm to improve canopy closing action. The roller bears on the inside surface of the cockpit coaming and prevents cocking outward of the left rear corner of the canopy when it is pushed closed with the external canopy handle.

The roller assembly will be a standard part of all 915 Canopy Kits delivered in the future, and it can be installed easily on any existing canopy with hand tools. We recommend that all Eagle II aircraft builders and owners make the installation. Installation instructions are included in Revision 6 of the 915 Canopy Kit product manual which was issued 01-13-83.

Following is a list of all parts required for the canopy roller installation along with the current prices. All parts are available immediately from factory stock:

PART NO.	DESCRIPTION	UNIT	QTY REQD	UNIT PRICE	AMOUNT
30589-012	SPACER, RECTANGULAR	EA	5		
31051-001	BODY, CANOPY GUIDE	EA	1		
31052-001	ROLLER, CANOPY GUIDE	EA	1		
50067-012	BOLT, UNDRILLED	EA	1		
50070-006	WASHER, FLAT	EA	4		
50241-001	NUT, THIN SELF-LOCKING	EA	1		
50843-003	SCREW, SOCKET SHOULDER	EA	1		

ENCLOSURES:

NONE