

No: 000292

CHRISTEN INDUSTRIES, INC.
1048 SANTA ANA VALLEY ROAD
HOLLISTER, CALIFORNIA 95023
TELEPHONE: (408) 637-7405

By: FLC Date: 02-21-83 Page: 1 of 1

Send To: 916 ENGINE MOUNT KIT

C-0002

C CHRISTEN INDUSTRIES INC.
U 1048 SANTA ANA VALLEY RD.
S HOLLISTER, CA 95023
T

Subject: BENDIX MAGNETO SERVICE
BULLETIN 623 WHICH MAY
APPLY TO LYCOMING ENGINES
USED IN EAGLE II AIRCRAFT

Enclosed is a copy of the subject service bulletin. All Eagle II aircraft builders and owners should read the bulletin carefully to determine if it applies to the magnetos on their Lycoming engines.

Parts requests, warranty requests, and questions concerning the bulletin directives should be directed to the nearest Bendix Corporation dealer, distributor or factory representative. A list of authorized Bendix distributors and branch offices is enclosed for reference.

The subject bulletin was received at Christen in October of 1982. No action was taken to notify Eagle II builders of the bulletin at that time because it was assumed that all registered owners of Lycoming engines would receive notice from either Lycoming or the FAA. No notice was made by these agencies.

Christen will continue to forward manufacturer's and FAA bulletins to Eagle II builders and owners, but we cannot accept responsibility for communicating all information which may affect Eagle II aircraft components. Accordingly, all Eagle II builders and owners should become familiar with the FAA's airworthiness directives system and should regularly review directives which may apply to their aircraft. All FAA approved aircraft service operators have copies of airworthiness directives available.

ENCLOSURES:

BENDIX SERVICE BULLETIN 623
LIST OF BENDIX DISTRIBUTORS AND BRANCHES