

No: 000217

CHRISTEN INDUSTRIES, INC.
1048 SANTA ANA VALLEY ROAD
HOLLISTER, CALIFORNIA 95023
TELEPHONE: (408) 637-7405

By: FLC Date: 04-22-81 Page: 1 of 1

Send To: 915 CANOPY KIT

C-0002
C CHRISTEN INDUSTRIES INC.
U 1048 SANTA ANA VALLEY RD.
S HOLLISTER, CA 95023
T

Subject: POSSIBILITY OF INCORRECT
PARTS IN 915 CANOPY KIT

The 915 Canopy Kit normally contains the following link-type parts:

1 ea 30311-501 Link Assembly
1 ea 30314-501 Link Assembly
1 ea 30314-502 Link Assembly
1 ea 30314-503 Link Assembly

Due to a packaging error, there is a possibility that your 915 kit may have been shipped to you with two each 30311-501 parts in place of one each 30314-501 and one each 30314-503.

If your canopy kit has not been installed, -please check your kit contents carefully to verify that you have the proper quantity of each of the above parts. If any parts are missing, please telephone the Christen factory collect and request that a replacement part be sent to you immediately via first class mail.

Enclosures:

None