

CHRISTEN \*

PRODUCT LETTER

No: 000111

CHRISTEN INDUSTRIES, INC.  
1048 SANTA ANA VALLEY ROAD  
HOLLISTER, CALIFORNIA 95023  
TELEPHONE: (408) 637-7405

By: IC

Date: 11-29-79

Page: 1 of 1

Applies: 918 ENGINE EQUIPMENT KIT

C-0002

C CHRISTEN INDUSTRIES INC.  
U 1048 SANTA ANA VALLEY RD.  
S HOLLISTER, CA 95023  
T

Subject: PROCEDURE ERROR IN 918  
MANUAL STEP F-13

PARAGRAPH 1 OF STEP F-13 DESCRIBES THE LOCATION AND DRILLING OF A HOLE IN THE UPPER LEFT ENGINE MONT GUSSET FOR ATTACHMENT OF THE ENGINE GROUND STRAP. THIS DRILLING PROCEDURE SHOULD BE ACCOMPLISHED BEFORE THE LEFT REAR BAFFLE ASSEMBLY IS INSTALLED IN UNIT C.

MAKE A NOTE IN YOUR MANUAL AT THE BEGINNING OF STEP C-2 TO DRILL THE HOLE DESCRIBED IN STEP F-13, PARAGRAPH 1.

THIS RELOCATION OF THE HOLE DRILLING PROCEDURE FROM UNIT F TO UNIT C WILL APPEAR IN THE NEXT 918 MANUAL REVISION.

ENCLOSURES:

NONE