

No: 000115

CHRISTEN INDUSTRIES, INC.
1048 SANTA ANA VALLEY ROAD
HOLLISTER, CALIFORNIA 95023
TELEPHONE: (408) 637-7405

By: IC

Date: 12-12-79

Page: 1 of 1

Applies: 918 ENGINE EQUIPMENT KIT

C-0002

C CHRISTEN INDUSTRIES INC.
U 1048 SANTA ANA VALLEY RD.
S HOLLISTER, CA 95023
T

Subject: PART NUMBER 31029-001
ENGINE BAFFLE PILOT HOLE
LOCATION

DUE TO A MANUFACTURING ERROR, THE BOTTOM HOLE OF THE THREE PILOT HOLES LOCATED ON THE INBOARD VERTICAL FLANGE OF THE 31029-001 ENGINE BAFFLE IS INCORRECTLY POSITIONED 2-5/16 INCHES BELOW THE TOP EDGE OF THE BAFFLE.

A NEW 1/16 INCH DIAMETER PILOT HOLE SHOULD BE DRILLED 3-5/16 INCHES BELOW THE TOP EDGE OF THE BAFFLE. ALL FOUR PILOT HOLES MAY BE USED FOR THE RIVETING PROCEDURE IN MANUAL STEP C-14. NORMALLY ONLY THREE HOLES ARE USED.

ENCLOSURES:

NONE