

CHRISTEN *

PRODUCT LETTER

No: 000163

CHRISTEN INDUSTRIES, INC.
1048 SANTA ANA VALLEY ROAD
HOLLISTER, CALIFORNIA 95023
TELEPHONE: (408) 637-7405

By: IC Date: 05-27-80 Page: 1 of 1

Send To: 904 FUSELAGE KIT

C-0002

C CHRISTEN INDUSTRIES INC.
U 1048 SANTA ANA VALLEY RD.
S HOLLISTER, CA 95023
T

Subject: REPOSITIONING OF NUTPLATE
TABS AT STATION 31 OF 904
FUSELAGE STRUCTURE

The locations and/or positions of several nutplate tabs on the 904 Fuselage Structure have been changed to allow more convenient installation of several parts in later kits.

The nutplate which is located at fuselage station 31 for attachment of the cushioned clamp which holds the electrical wiring harness has been repositioned to face inboard rather than outboard as on earlier fuselages. This change does not alter the position or function of the tab, and the original position is entirely satisfactory.

If the tab at station 31 on your fuselage structure faces in a direction different from that shown in your product manual, disregard the manual depiction and proceed with assembly of the aircraft by simply repositioning the the harness clamp to mount on the most convenient side of the tab.

Enclosures:

None