

CHRISTEN *

PRODUCT LETTER

No: 000184

CHRISTEN INDUSTRIES, INC.
1048 SANTA ANA VALLEY ROAD
HOLLISTER, CALIFORNIA 95023
TELEPHONE: (408) 637-7405

By: IC Date: 11-04-80 Page: 1 of 1

Send To: 918 ENGINE EQUIPMENT KIT

C-0002
C CHRISTEN INDUSTRIES INC.
U 1048 SANTA ANA VALLEY RD.
S HOLLISTER, CA 95023
T

Subject: CHANGED HARDWARE FOR
ATTACHMENT OF GOVERNOR
CONTROL CABLE TO GOVERNOR
CONTROL ARM

The hardware used to attach the governor control cable to the governor control arm which is listed in manual step G-23 has been changed. A 30146-027 washer is now installed under the head of the 50067-010 bolt in place of the 50132-003 washer originally shown. In addition, a 50070-006 washer is now installed between the new 30146-027 washer and the rod end bearing.

These changes will be included in the next 918 manual revision. One 30146-027 washer and one 50070-006 washer are being mailed to all Eagle aircraft builders to whom the 918 kit has been shipped.

Enclosures:

1 ea 30146-027 washer
1 ea 50070-006 washer