

No: 000251

CHRISTEN INDUSTRIES, INC.
1048 SANTA ANA VALLEY ROAD
HOLLISTER, CALIFORNIA 95023
TELEPHONE: (408) 637-7405

By: IC Date: 02-15-82 Page: 1 of 1

Send To: 908 COCKPIT EQUIPMENT KIT

C-0002

C CHRISTEN INDUSTRIES INC.
U 1048 SANTA ANA VALLEY RD.
S HOLLISTER, CA 95023
T

Subject: NEW HARDWARE FOR ATTACH-
MENT OF RUDDER CABLE
CLEVISES TO RUDDER HORNS

The 50133-036 clevis pins used to attach the rudder cable clevises to the rudder horn have been replaced by 50825-011 clevis bolts and 50826-003 castle nuts. This change has been made for compliance with Federal Aviation Regulations Part 23.689 which reads in part: "Clevis pins subject to load or motion and retained only by cotter pins may not be used in the control system."

The 908 Product Manual is being revised and all future 908 Kits will include the new attachment hardware.

Eagle builders who have received their 908 Kit should discard the 2 ea 50133-036 clevis pins and should use the enclosed hardware to attach the rudder cables to the rudder horns of their aircraft.

Enclosures:

2 ea 50825-011 Clevis bolt
2 ea 50826-003 Castle nut
2 ea 50070-006 Washer
2 ea 50131-001 Cotter pin